

Oil Field Environmental Incident Summary

Incident: 20150128155306 **Date/Time of Notice:** 01/28/2015 15:53

Responsible Party: ONEOK Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Stateline Compressor Station

Field Name:

Well File #:

Date Incident: 1/27/2015 **Time Incident:** 0800

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 102

Sec: 10

Qtr: NE

Location Description: Stateline Compressor Station
14312 59th St NW
Williston, ND 58801

Submitted By: Kimberly Rudningen

Received By:

Contact Person: Kimberly Rudningen
2700 Lincoln Ave SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	0.5	Gallons				

Description of Other Released Contaminant:

Natural gas condensates

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There are no immediated environmental or health risks associated with this release.

Areal Extent:

This release was contained to the to a small area of gravel and sand inside the compressor building.

Potential Environmental Impacts:

There are no impacts to offsite surface water or soil.

Action Taken or Planned:

Plans for remediation includes in-place remediation using a granular hydrocarbon remediation product as well as removal of some soil to a sealed container for disposal.

Wastes Disposal Location: Any recovered waste will be disposed of in a certified disposal landfill.

Agencies Involved:**Updates**

Date: 1/29/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted an area that doesn't fall under E & P locations. Followup is necessary.

Date: 4/2/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

4/2/2015 at 13:54, on location. No visible staining leading from compressor building.